



1



P13 3,5x13 x7

F40 x5

L50 L-max x1

T1 x16

S11 4x25 x10








L52 L-min x2

B1 ϕ 8x28 x12











M1 x12

R11 L-345 mm x1










E4 6,0x8,0 x2






2




3




5




6




7



8



9



10

