







0 10 20 30 40 50 60mm

B1		$\phi 8 \times 28$	x16
M1			x16
C2		x...(16)	
T1		x16	
W1		x12	
P13		$3,5 \times 13$	x2
Y1		$\phi 26$ KR15	x5
Y5		H2	x5
E1		$6,3 \times 13$	x10
S8		4×13	x10
F40			x4
L50		L-max	x1
S11		4×25	x8
L52		L-min	x2
L10			x2






1





2




3



4




5







6

J23	x12
P3	3,5x18 x5



7




x1



x1




4x45



3,5x13



x2



x...(16)

